

STATUS REPORT OF CONSTRUCTION, PROGRESS CHECKING OPERATIONS, DISASTER SITE, ETC.

FIG. 1 PRIOR ART


DOBUDARY DEDECO

FIG. 2

PRIOR ART

FIG. 3

PRIOR ART






FIG. 4




FIG. 5

FIG. 6





FIG. 7




OSEINSEL OSOISO


SHADED FRAMES INDICATE THAT SUFFICIENT QUALITIES ARE NOT GIVEN DUE TO NARROW-BAND

NOTE NOTE

IMAGE TRANSMISSION

3






DONWOODF DOUDD


NOTE

At IS SAMPLING FREQUENCY. IN CASE OF NTSC STANDARD 1/29.97 Hz = APPROXIMATELY 33.37 msec SHADED FRAMES INDICATE THAT SUFFICIENT QUALTY IS NOT GIVEN DUE TO NARROW-BAND


NOTE

IMAGE TRANSMISSION





SCREEN OBTAINED BY REDUCING AND SYNTHESIZING 4 FRAMES



SCREEN OBTAINED BY REDUCING AND SYNTHESIZING 9 FRAMES

FIG. 13A

FIG. 13B


ogsabaet cecan


NOTE NOTE

IMAGE TRANSMISSION

SHADED FRAMES INDICATE THAT SUFFICIENT QUALITY IS NOT GIVEN DUE TO NARROW - BAND

At IS SAMPLING FREQUENCY. IN CASE OF NTSC STANDARD 1/29.97 Hz = APPROXIMATELY 33.37 msec









FIG. 17



COMWOGAL CACKOO

NOTE


At IS SAMPLING FREQUENCY. IN CASE OF NTSC STANDARD 1/29.97 Hz = APPROXIMATELY 33.37 msec


SHADED FRAMES INDICATE THAT SUFFICIENT QUALITY IS NOT GIVEN DUE TO NARROW-BAND

NOTE

IMAGE

TRANSMISSION





## DOBLOSH. DECED

